



HVBS-712 Metal Bandsaw

HVBS-712.... 414559-RU~230V, 50Hz

HVBS-712....414559-3RU....3~400V, 50Hz

PARTS LIST



JPW Tool Group Hong Kong Limited
98 Granville Road, Tsimshatsui East, Kowloon, Hong Kong, PRC
www.jettools.com


Импортёр в РФ: ООО «ИТА Технолоджи»
105082, Москва, Переведеновский пер., д. 17
www.jettools.ru

Made in Taiwan / Сделано на Тайване


P-414559-RU/3RU

2022-11

Base Breakdown for HVBS-712



Bow Breakdown for HVBS-712



HVBS-712 Bandsaw Part List

| Index | Part | | Description | Size | Q'ty |
|--------------|--------------|--|---------------------------------------------|-------------|-------------|
| No. | No. | | | | |
| | HVBS712-SA | | Stand Assembly (includes #1 thru 5) | | 1 |
| 1..... | HVBS712-01 | | Water Tray | | 1 |
| 2..... | HVBS712-02 | | Stand - Left | | 1 |
| 3..... | HVBS712-03 | | Stand - Right | | 1 |
| 4..... | HVBS712-04 | | Front Plate | | 1 |
| 5..... | HVBS712-05 | | Pump Support Plate | | 1 |
| 6..... | HVBS712-06 | | Shipping Brace (for shipping purposes only) | | 2 |
| 7..... | TS-0051011E | | Hex. Cap Screw | 5/16"x1/2" | 2 |
| 9..... | HVBS7MW-166E | | Round Head Screw | 3/16"x3/8" | 2 |
| 10..... | HVBS7MW-165E | | Cover | | 1 |
| 16..... | HVBS712-16 | | Knob | 1/4"x1/2" | 1 |
| 20..... | HVBS7MW-13N | | Cylinder Assembly | | 1 |
| 21..... | TS-1505061E | | Socket Head Cap Screw | M10x40 | 1 |
| 22..... | TS-1550071E | | Flat Washer | M10 | 1 |
| 24..... | TS-1540071E | | Nut | M10 | 1 |
| 25..... | TS-0208041E | | Hex. Cap Screw | 5/16"x3/4" | 4 |
| 26..... | TS-0720081E | | Lock Washer | 5/16" | 4 |
| 27..... | HVBS712-27 | | Cylinder Support Shaft | | 1 |
| 28..... | TS-0267041E | | Set Screw | 1/4"x3/8" | 1 |
| 29..... | HVBS712-29 | | Lower Cylinder Support | | 1 |
| 33..... | TS-0680081N | | Flat Washer | 5/8" | 4 |
| 34..... | 5518229N | | Wheel | 8" | 4 |
| 35..... | HVBS712-35 | | Wheel Shaft | | 2 |
| 36..... | 5518231N | | Cotter Pin | | 4 |
| 39..... | HVBS712-39 | | Bed | | 1 |
| 39-1..... | HVBS712-39-1 | | Strain Relief | MG16A-10B | 1 |
| 39-2..... | HVBS712-39-2 | | Wire Grip | | 1 |
| 39-3..... | HVBS712-39-3 | | Round Head Screw | 3/16"x3/8" | 1 |
| 40..... | TS-0051051E | | Hex. Cap Screw | 5/16 "x1" | 5 |
| 41..... | TS-0680031E | | Flat Washer | 5/16" | 6 |
| 42..... | TS-0720081E | | Lock Washer | 5/16" | 6 |
| 43..... | TS-0561021E | | Nut | 5/16" | 6 |
| 44..... | HVBS7MW-29 | | Filter Assembly | | 1 |
| 47..... | HVBS712-47 | | Handwheel | | 1 |
| 48..... | TS-0270031E | | Set Screw | 5/16"x3/8" | 1 |
| 49..... | HVBS712-49 | | Round Key | 5x20 | 1 |
| 50..... | HVBS712-50 | | Lead Screw | | 1 |
| 51N..... | HVBS7MW-35 | | Nut Seat | | 1 |
| 54..... | HVBS712-54 | | Table Plate | | 1 |
| 56..... | TS-0680031E | | Flat Washer | 5/16" | 2 |
| 57..... | TS-0051031E | | Hex. Cap Screw | 5/16"x5/8" | 2 |
| 58..... | TS-0720081E | | Lock Washer | 5/16" | 2 |
| 59..... | HVBS7MW-37 | | Support Plate | | 1 |
| 60..... | HVBS7MW-38 | | Stop Screw | | 1 |
| 61..... | TS-0561021E | | Nut | 5/16" | 2 |
| 62..... | HVBS712-62 | | Plastic Knob | M12 | 1 |
| 63..... | TS-1540081E | | Nut | M12 | 1 |
| 63-1..... | TS-2360121E | | Flat Washer | M12 | 2 |
| 64..... | HVBS7MW-41 | | 90 Degree Support | | 1 |


| Index | Part | | Description | Size | Q'ty |
|--------------|--------------------|--|------------------------------------------|---------------|-------------|
| No. | No. | | | | |
| 64-1 | HVBS7MW-151..... | | Support Screw..... | | 1 |
| 64-2 | HVBS7MW-152..... | | Bracket..... | | 1 |
| 64-3 | HVBS7MW-153..... | | Spring..... | | 1 |
| 64-4 | HVBS7MW-154..... | | Spring Cap | | 1 |
| 64-5 | HVBS7MW-155..... | | Socket Head Cap Screw..... | 3/16"x1/2" | 1 |
| 64-6 | TS-0720091E..... | | Lock Washer | 3/8" | 1 |
| 64-7 | TS-0561031E..... | | Hex. Nut | 3/8" | 1 |
| 65 | TS-0561031E..... | | Hex. Nut | 3/8" | 2 |
| 66 | TS-0720091E..... | | Lock Washer | 3/8" | 2 |
| 67 | TS-0060071E..... | | Hex. Cap Screw..... | 3/8"x1-1/2" | 2 |
| 81 | HVBS712-81..... | | Pivot Arm..... | | 1 |
| 82 | HVBS712-82..... | | Support Shaft | Ø22 | 1 |
| 82-1 | HVBS712-82-1..... | | Spacer..... | | 1 |
| 83 | HVBS712-83..... | | Locking Nut | 1/2" | 2 |
| 83N | TS-0680061E..... | | Flat Washer | 1/2" | 2 |
| 84 | HVBS7MW-60..... | | Arm Support Plate | | 1 |
| 85 | TS-0720091E..... | | Lock Washer | 3/8" | 2 |
| 86 | TS-0060071E..... | | Hex. Cap Screw..... | 3/8"x1-1/2" | 2 |
| 87 | HVBS712-87..... | | Extension Spring | | 1 |
| 88 | HVBS7MW-54..... | | Spring Adjusting Rod | | 1 |
| 89 | HVBS712-89..... | | Spring Bracket | | 1 |
| 90 | TS-0051051E..... | | Hex. Cap Screw..... | 5/16"x1" | 2 |
| 91 | TS-0561031E..... | | Nut | 3/8" | 1 |
| 92 | TS-0720081E..... | | Lock Washer | 5/16" | 1 |
| 92-1 | TS-0680031E..... | | Flat Washer | 5/16" | 1 |
| 93 | TS-0561021E..... | | Hex. Nut | 5/16" | 1 |
| 94 | HVBS712-94..... | | Vise Jaw - Left | | 1 |
| 95 | HVBS7MW-58..... | | Vise Jaw - Right | | 1 |
| 96 | TS-0060071E..... | | Hex. Cap Screw | 3/8"x1-1/2" | 1 |
| 96-1 | TS-0680041E..... | | Flat Washer | 3/8" | 1 |
| 96-3 | TS-0720091E..... | | Lock Washer | 3/8" | 2 |
| 97 | TS-0209061E..... | | Hex Cap Screw | 3/8"x1-1/4" | 1 |
| 98 | TS-0070031E..... | | Hex. Cap Screw | 1/2"x1-1/2" | 1 |
| 98-1 | TS-0720111E..... | | Lock Washer | 1/2" | 2 |
| 98-2 | TS-0680061E..... | | Flat Washer | 1/2" | 1 |
| 99 | TS-0100041E..... | | Hex. Cap Screw | 1/2"x1-1/4" | 1 |
| 100-1 ... | HVBS712-100-1..... | | Scale | | 1 |
| 101 | TS-0209081E..... | | Socket Head Cap Screw | 3/8"x1-3/4" | 1 |
| 101-1 ... | TS-0561031E..... | | Nut | 3/8" | 1 |
| 101-2 ... | TS-0680041E..... | | Flat Washer | 3/8" | 1 |
| 102 | HVBS712-102W..... | | Hose | 1" | 1 |
| 103 | HVBS712K-63E..... | | Coolant Pump | 230V/1Ph/50Hz | 1 |
| | HVBS712K-63AE..... | | Coolant Pump | 400V/3Ph/50Hz | 1 |
| 104 | TS-0050031E..... | | Hex. Cap Screw | 1/4"x3/4" | 2 |
| 107 | HVBS712-107N..... | | Coolant Tank | | 1 |
| 109 | HVBS7MW-68..... | | Hose Clamp | 13mm | 1 |
| 110 | HVBS712-110W..... | | Hose | 5/16" | 1 |
| 111 | HVBS712-111W..... | | Bow | | 1 |
| 112N ... | HVBS7MW-160..... | | Hex Cross Head Bolt W/ Lock Washer | 1/4" x 1/2" | 4 |
| 113 | HVBS7MW-71..... | | Vent Plug | | 1 |
| 114N ... | HVBS7MW-72G..... | | Gear Box Cover | | 1 |
| 115N ... | HVBS7MW-73..... | | Gear Box Gasket | | 1 |

| Index | Part | | Description | Size | Q'ty |
|--------------|---------------------|--|-----------------------------------------|-----------------------|-------------|
| No. | No. | | | | |
| 116..... | HVBS712-116N..... | | Worm Gear..... | | 1 |
| 116-1... | HBS916W-49..... | | C-Ring..... | S25..... | 3 |
| 117..... | HVBS7MW-142..... | | Key..... | 6x6x20..... | 1 |
| 118..... | BB-6005Z..... | | Ball Bearing | 6005..... | 3 |
| 119..... | F006229E | | Hex Cap Screw..... | 3/8"-16 x 7/8" | 1 |
| 119-1 ... | TS-0720091E | | Lock Washer | 3/8" | 1 |
| 119-2... | HVBS7MW-145..... | | Flat Washer..... | 3/8"x35x4 | 1 |
| 120..... | HVBS7MW-78..... | | Oil Seal | 25. 47. 7 | 1 |
| 121N ... | HVBS7MW-79G | | Gear Box | | 1 |
| 122..... | TS-0720081E | | Lock Washer | 5/16" | 4 |
| 123..... | TS-0081051 | | Hex. Cap Screw..... | 5/16"x1-1/4" | 4 |
| 123-1 ... | TS-0207072E | | Socket Cap Screw | 1/4x1/4" | 2 |
| 124..... | HVBS7MW-80N | | Blade Drive Wheel..... | | 1 |
| 125..... | HVBS7MW-81..... | | Worm Bushing..... | | 1 |
| 126..... | TS-0206021E | | Socket Head Cap Screw..... | 3/16"x3/8" | 3 |
| 127..... | HVBS7MW-82..... | | Bi-Metal Blade | 19x0.9x2362mm 5/8T .. | 1 |
| 128..... | HVBS712-128W | | Rear Guard | | 1 |
| 129..... | HVBS7MW-83..... | | Wheel Cover..... | | 1 |
| 130..... | HVBS7MW-160..... | | Hex Cross Head Bolt W/ Lock Washer..... | 1/4" x 1/2" | 2 |
| 130-1 ... | TS-0680021E | | Flat Washer..... | 1/4" | 2 |
| 131..... | HVBS7MW-86..... | | Lock Knob | | 2 |
| 131-1 ... | TS-0680041E | | Flat Washer | 3/8" | 2 |
| 132-1 ... | HVBS7MW-87..... | | Adjustable Bracket - Right | | 1 |
| 133..... | BB-608ZZ | | Ball Bearing | 608ZZ | 2 |
| 134..... | HVBS712-134W | | Adjustable Blade Seat - Right | | 1 |
| 135..... | HVBS7MW-90..... | | Bearing Pin | | 2 |
| 136..... | HVBS7MW-91..... | | Eccentric Shaft Assembly (outside)..... | | 2 |
| 136-1 ... | HVBS7MW-91A | | Center Shaft Assembly (inside)..... | | 2 |
| 137..... | TS-0561031E | | Hex. Nut | 3/8"x24UNF | 4 |
| 137-1 ... | TS-0720091E | | Lock Washer | 3/8" | 4 |
| 138..... | TS-0680031E | | Flat Washer | 5/16" | 2 |
| 139..... | TS-0720081E | | Lock Washer | 5/16" | 2 |
| 140..... | HVBS712-140W | | Hex. Socket Cap Screw..... | 5/16"x1-1/8" | 1 |
| 141..... | HVBS712-141W | | Flat Pan Head Screw..... | 1/4"x3/8" | 2 |
| 142..... | HVBS7MW-94..... | | Vertical Cutting Plate | | 1 |
| 143..... | HVBS712-143W | | Adjustable Blade Seat - Left..... | | 1 |
| 144..... | TS-0209032E | | Hex. Cap Screw..... | 3/8"x3/4" | 2 |
| 145..... | HVBS712-145N..... | | Upper Cylinder Support | | 1 |
| 146..... | TS-0720091E | | Lock Washer | 3/8" | 2 |
| 148..... | TS-0813032E | | Round Head Screw..... | 1/4"x1/2" | 2 |
| 149..... | TS-0680021E | | Flat Washer | 1/4" | 2 |
| 150..... | HVBS712-150N..... | | Brush Holder | | 1 |
| 151..... | TS-0051071E | | Hex. Cap Screw | 5/16"x1-1/2" | 2 |
| 152..... | TS-0561021E | | Nut | 5/16" | 2 |
| 153..... | HVBS7MW-100..... | | Wire Brush | | 1 |
| 154..... | TS-0051021E | | Hex. Cap Screw..... | 5/16"x5/8" | 3 |
| 154-1 ... | TS-0720081E | | Lock Washer | 5/16" | 3 |
| 155..... | TS-0267021E | | Set Screw | 1/4" | 1 |
| 156..... | HVBS7MW-109..... | | Brush Support | | 1 |
| 157..... | HVBS712-157W | | Bearing Bushing - Left | | 1 |
| 163-1 ... | HVBS712-163-1 | | Adjustable Bracket - Left..... | | 1 |
| 164..... | HVBS712-164W | | Blade Guard | | 1 |

| Index | Part | | Description | Size | Q'ty |
|--------------|----------------|--|------------------------------------------------|---------------|-------------|
| No. | No. | | | | |
| 164-1 | HVBS712-164-1 | | Round Head Screw..... | 3/16"x1/4 " | 2 |
| 165 | TS-0050011E | | Hex. Cap Screw..... | 1/4"x1/2" | 4 |
| 166 | HVBS7MW-111 | | Guide Plate | | 2 |
| 167 | TS-0270071E | | Set Screw..... | 5/16" x3/4" | 1 |
| 168 | TS-0051071E | | Hex. Cap Screw..... | 5/16"x1-1/2" | 2 |
| 169 | HVBS7MW-114 | | Blade Tension Block..... | | 1 |
| 170 | TS-0050011E | | Hex. Cap Screw..... | 1/4"x1/2" | 1 |
| 170-1 | TS-0720071E | | Lock Washer | 1/4" | 1 |
| 170-2 | TS-0680021E | | Flat Washer..... | 1/4" | 1 |
| 171 | HVBS712-171 | | Sliding Draw Block..... | | 1 |
| 172 | HVBS7MW-164 | | Fix Bracket (for shipping purposes only) | | 1 |
| 172-1 | TS-0561021E | | Nut | 5/16" | 1 |
| 173 | HVBS712-173W | | Bearing Bushing - Right..... | | 1 |
| 174 | BB-6203ZZ | | Ball Bearing..... | 6203ZZ | 2 |
| 175 | HVBS7MW-119 | | Blade Idler Wheel | | 1 |
| 176 | TS-0680031E | | Flat Washer..... | 5/16" | 1 |
| 176-1 | TS-0720081E | | Lock Washer | 5/16" | 1 |
| 177 | TS-0081031E | | Hex. Cap Screw..... | 5/16"x3/4" | 1 |
| 178 | TS-081F031E | | Round Head Screw..... | 1/4"x1/2" | 2 |
| 179 | TS-0680021E | | Flat Washer | 1/4" | 2 |
| 180 | TS-0680041E | | Flat Washer | 3/8" | 1 |
| 181 | HVBS712-181W | | Blade Tension Handle | | 1 |
| 183 | VB-3V270 | | V-Belt | 3V270 | 1 |
| 184 | HVBS7MW-123 | | Worm Pulley | | 1 |
| 185 | HVBS7MW-124 | | Motor Pulley | | 1 |
| 186 | TS-0270031E | | Set Screw | 5/16"x3/8" | 3 |
| 187 | TS-0050011E | | Hex. Cap Screw..... | 1/4"x1/2" | 2 |
| 188 | TS-0680021E | | Flat Washer | 1/4" | 2 |
| 189 | HVBS7MW-126 | | Pulley Cover | | 1 |
| 190 | HVBS7MW-160 | | Hex Cross Head Bolt W/ Lock Washer..... | 1/4"x1/2" | 1 |
| 190-1 | TS-0680021E | | Flat Washer | 1/4" | 1 |
| 191 | HVBS7MW-141 | | Key | 5x5x20 | 1 |
| 192 | HVBS712K-129E | | Motor..... | 230V/1Ph/50Hz | 1 |
| | HVBS712K-129AE | | Motor..... | 400V/3Ph/50Hz | 1 |
| | HVBS712K-129A | | Motor Fan (not shown)..... | | 1 |
| | HVBS712K-129B | | Motor Fan Cover (not shown) | | 1 |
| | HVBS712K-129C | | Motor Centrifugal Switch (not show)..... | 230V/1Ph/50Hz | 1 |
| | HVBS712K-129D | | Condenser (not shown)..... | 230V/1Ph/50Hz | 1 |
| 193 | TS-0081051E | | Hex. Cap Screw | 5/16"x1" | 4 |
| 194 | HVBS7MW-130G | | Motor Mount Plate (Upper)..... | | 1 |
| 194-1 | HVBS7MW-138G | | Motor Support Plate (Bottom) | | 1 |
| 195 | TS-0680031E | | Flat Washer | 5/16" | 4 |
| 196 | TS-0720081E | | Lock Washer | 5/16" | 4 |
| 197 | TS-0561021E | | Hex. Nut | 5/16" | 4 |
| 199 | BB-6003Z | | Ball Bearing..... | 6003 | 3 |
| 200 | HVBS7MW-162 | | Block Plate | | 1 |
| 201 | HVBS7MW-134 | | Oil Seal | 17.35.7 | 1 |
| 202 | HVBS7MW-135 | | Bearing Bushing | | 1 |
| 203N | HVBS712-203N | | Worm Shaft | | 1 |
| 203-1 | HVBS7MW-131 | | C-Ring | S17 | 1 |
| 204 | HVBS7MW-204 | | Hex. Cap Screw | 1/4"x3/8" | 2 |
| 205 | TS-0680021E | | Flat Washer | 1/4" | 2 |

| Index | Part | | | |
|--------------|----------------|----------------------------------------------------|-----------------------|-------------|
| No. | No. | Description | Size | Q'ty |
| 206 | HVBS7MW-137 | Rubber Flap..... | | 1 |
| 207 | HVBS7MW-116 | Switch Cut-Off Bracket..... | | 1 |
| 210 | TS-0680021E | Flat Washer..... | 1/4" | 1 |
| 211 | TS-0720071E | Lock Washer | 1/4" | 1 |
| 212 | TS-0050011E | Hex. Cap Screw..... | 1/4"x1/2" | 1 |
| 213 | TS-0561021E | Hex. Nut | 5/16" | 1 |
| 214 | TS-0051071E | Hex Cap Screw..... | 5/16"x1-1/2" | 1 |
| 217 | HVBS7MW-77 | C-Ring..... | R47 | 2 |
| 218 | HVBS7MW-101 | Nozzle Cock | | 1 |
| 219 | TS-0267021E | Set Screw..... | 1/4"x1/4" | 1 |
| 220 | HVBS712-103-1 | Nozzle Cock Support..... | | 1 |
| 221 | HVBS7MW-104 | Valve | | 1 |
| 222 | HVBS710S-166 | Hex. Socket Cap Screw..... | 5/16"x1-1/8" | 1 |
| 223 | HVBS712-218W | Left Blade Guide Assembly..... | | 1 |
| 224 | HVBS712-219W | Right Blade Guide Assembly | | 1 |
| 225 | HVBS7MW-152A | Arm Stop Assembly CP (incl. #64-1 thru 64-5) | | 1 |
| 226 | HVBS7MW-44 | Thumb Screw | | 1 |
| 227 | HVBS7MW-45 | Stop Block | | 1 |
| 228 | HVBS7MW-46 | Stop Rod | | 1 |
| 229 | HVBS7MW-161E | Limit Switch Seat | | 1 |
| 230 | HVBS7MW-162E | Round Head Screw..... | 3/16"x3/8" | 2 |
| 231 | HVBS7MW-163E | Cut Off Limit Switch (LS1)..... | | 1 |
| 232 | HVBS7MW-164E | Round Head Screw..... | 3/16"x1" | 2 |
| 233 | HVBS712K-170E | Magnetic Switch (S)..... | 1 Ph | 1 |
| | HVBS712K-170AE | Magnetic Switch (S)..... | 3Ph | 1 |
| | HVBS712K-MR-1 | Magnetic Relay (not show)..... | 1PH 230V | 1 |
| | HVBS712K-MR-3 | Magnetic Relay (not show)..... | 3PH 400V | 1 |
| | HVBS712K-CPS | Coolant Pump Switch (not show) | | 1 |
| 234 | HVBS7MW-171E | Round Head Screw..... | 3/16"x45 | 1 |
| 235 | HVBS7MW-173E | Support Plate..... | | 1 |
| 236 | HVBS7MW-172E | Round Head Screw..... | 3/16"x3/8" | 3 |
| 237 | HVBS7MW-180E | Wheel Cover Limit Switch..... | | 1 |
| 238 | HVBS7MW-181E | Round Head Screw..... | 3/16"x1" | 2 |
| 239 | HVBS7MW-182E | Hex. Socket Cap Screw..... | 3/16"x3/8" | 2 |
| 240 | HVBS7MW-183E | Spring Washer..... | 3/16" | 2 |
| 241 | HVBS7MW-184E | Limit Switch Bracket | | 1 |
| 242 | HVBS712-242 | Limit Switch Stop Plate | | 1 |
| 243 | HVBS712-243 | Lock Washer | 3/16" | 2 |
| 244 | HVBS712-244 | Hex. Socket Cap Screw..... | 3/16"x3/8" | 2 |
| 245 | HVBS712-245 | Cover | | 1 |
| 246 | HVBS712-246 | Round Head Screw..... | 1/4"x1/2" | 1 |
| | JET-113 | JET Logo with 3M Adhesive (not shown) | 113 x 47mm | 1 |
| | HVBS712K-26E | Power Cord (not shown) | 3Gx1.5MM ² | 1 |
| | HVBS712K-26AE | Power Cord (not shown) | 4Gx1.0MM ² | 1 |


HVBS-712 ...414559-RU.... ~230V, 50Hz



| | colour of strands | Litzenfarben | couleur des cordons |
|------|-------------------|--------------|---------------------|
| BK | black | schwarz | noir |
| WH | white | weiß | blanc |
| BU | blue | blau | bleu |
| YE | yellow | gelb | jaune |
| RD | red | rot | rouge |
| BN | brown | braun | brun |
| GY | grey | grau | gris |
| GNYE | green-yellow | grün-gelb | vert-jaune |
| OG | orange | orange | orange |
| VT | violet | violett | violet |

| | meaning of symbol | Bedeutung der Zeichen | interprétation |
|-----|----------------------|--------------------------|------------------------------|
| M1 | motor | Motor | moteur |
| M2 | Coolant pump | Kühlmittelpumpe | Pompe de liquide réfrigérant |
| S | switch | Schalter | interrupteur |
| S4 | Pump switch | Kühlmittelpumpe Schalter | Commutateur de pompe |
| LS2 | limit switch | Positionsendschalter | micro |
| LS1 | cut-off limit switch | positionsendschalter | micro |

HVBS-712 ...414559-3RU.... 3~400V, 50Hz



| | colour of strands | Litzenfarben | couleur des cordons |
|------|-------------------|--------------|---------------------|
| BK | black | schwarz | noir |
| WH | white | weiß | blanc |
| BU | blue | blau | bleu |
| YE | yellow | gelb | jaune |
| RD | red | rot | rouge |
| BN | brown | braun | brun |
| GY | grey | grau | gris |
| GNYE | green-yellow | grün-gelb | vert-jaune |
| OG | orange | orange | orange |
| VT | violet | violett | violet |

| | meaning of symbol | Bedeutung der Zeichen | interprétation |
|-----|----------------------|--------------------------|------------------------------|
| M1 | motor | Motor | moteur |
| M2 | Coolant pump | Kühlmittelpumpe | Pompe de liquide réfrigérant |
| S | switch | Schalter | interrupteur |
| S4 | Pump switch | Kühlmittelpumpe Schalter | Commutateur de pompe |
| LS2 | limit switch | Positionendschalter | micro |
| LS1 | cut-off limit switch | positionsendschalter | micro |